

Deployment Date: 5/31/2019

Hot Fix: cp711_sys_053.zip; cp711_patch3654_001.zip; cp711_bmqwu_011.zip; cp711_ecpinecn_023.zip; cp711_ecrimpct_013.zip; cp711_mrpllc_008.zip

MATERIALS/ENGINEERING CHANGE NOTICES/ECPINECN/Implement ECN Changes

Deltek Defect Tracking Number:

1099436

Issues Resolved:

Description: When you changed the work center value in the ECN MBOM/EBOM component subtasks for different action codes (Change, New Revision) the revised work center was not updated/copied over to the BOM.

Customers Impacted: This defect affects Costpoint users.

Workaround Before Fix: Manually enter/update the work center on the Manage MBOM/EBOM applications.

Additional Notes: None.

Files Updated:

cp711_sys_053.zip

Patch3654.sql

cp711_bmqwu_011.zip

cp711_ecpinecn_023.zip

cp711_ecrimpct_013.zip

cp711_mrpllc_008.zip

System File Dependencies:

cp711_patch3629_001.zip

Custom Programs Affected:

Sometimes a hot fix can cause custom programs and reports to stop working as expected. Before applying this hot fix, consider whether you have any custom programs or reports in the application area affected by the hot fix. If so, contact Deltek support at <https://deltek.custhelp.com> before you install the hot fix.

To Download the Hot Fix:

1. From Internet Explorer, go to <https://dsm.deltek.com>.
2. Click Run Deltek Software Manager.
3. Log in using your Deltek Customer Care Connect credentials.
4. In the left pane of the Deltek Software Manager, expand your Deltek product.
5. Expand the Hotfix folder for your product, and select the hotfix to download.
6. Click Download at the bottom of the screen.

More Information:

If you have any questions, please contact Deltek support at <https://deltek.custhelp.com>.